

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2014

Levee District No. 0001 (Glenn County)

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	12.23	10/30/2014 10/30/2014	Bob Duffey

LM Start		Rating **	A	Issue No.	5
LM End		Issue Type +	Ma	Location *	LS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Operations & Maintenance Manuals			°	°
				°	°
DWR ID	DWR_LD0001G_01_s_2013_5				
Action/Comments					
Inspector Comments: The LMA has copies of the O&M manuals.					

No Photos

LM Start		Rating **	A	Issue No.	9
LM End		Issue Type +	Ma	Location *	LS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Emergency Supplies & Equipment			°	°
				°	°
DWR ID	DWR_LD0001G_01_s_2013_9				
Action/Comments					
Inspector Comments: The LMA has adequate emergency supplies and equipment.					

No Photos

LM Start		Rating **	A	Issue No.	14
LM End		Issue Type +	Ma	Location *	LS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Flood Preparedness & Training			°	°
				°	°
DWR ID	DWR_LD0001G_01_s_2013_14				
Action/Comments					
Inspector Comments: The LMA has completed flood fight training in the past.					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2014

Levee District No. 0001 (Glenn County)

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	12.23	10/30/2014 10/30/2014	Bob Duffey

LM Start	1.23	Rating **	M	Issue No.	1
LM End	1.23	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			39.493423 °	39.493423 °
				-122.018885 °	-122.018885 °
DWR ID	DWR_LD0001G_01_s_2012_1				
Action/Comments					
Debris					

Photo 1 of 1 : FA_2014_LD0001G_432_1_20141013_00001.jpg



View of the debris & garbage along the W/S toe.

LM Start	2.86	Rating **	A/W	Issue No.	50
LM End	2.86	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			39.509503 °	39.509503 °
				-122.008732 °	-122.008732 °
DWR ID	DWR_LD0001G_01_f_2014_50				
Action/Comments					
No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.					

Photo 1 of 1 : FA_2014_LD0001G_432_50_20141121_00041.jpg



View of the rodent activity along the landside slope.

LM Start	3.13	Rating **	C	Issue No.	26
LM End	3.13	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			39.513358 °	39.513358 °
				-122.009448 °	-122.009448 °
DWR ID	DWR_LD0001G_01_s_2012_26				
Action/Comments					
No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2014

Levee District No. 0001 (Glenn County)

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	12.23	10/30/2014 10/30/2014	Bob Duffey

LM Start	3.15	Rating **	M	Issue No.	51
LM End	3.15	Issue Type +	Ma	Location *	N/A
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			39.513485 °	39.513485 °
				-122.009593 °	-122.009593 °
DWR ID	DWR_LD0001G_01_f_2014_51				
Action/Comments					
No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.					

Photo 1 of 1 : FA_2014_LD0001G_432_51_20141121_00043.jpg



View of the rodent activity along the landside slope.

LM Start	3.22	Rating **	M	Issue No.	16
LM End	3.22	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			39.514378 °	39.514378 °
				-122.010306 °	-122.010306 °
DWR ID	DWR_LD0001G_01_s_2012_16				
Action/Comments					
Prunings					

Photo 1 of 1 : FA_2014_LD0001G_432_16_20141013_00009.jpg



View of the pruning pile along the L/S toe.

LM Start	3.93	Rating **	M	Issue No.	23
LM End	3.93	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			39.523660 °	39.523660 °
				-122.010863 °	-122.010863 °
DWR ID	DWR_LD0001G_01_s_2012_23				
Action/Comments					
Equipment					

No Photos

* Location
LS : Land Side N/A : Not Applicable
WS : Water Side
CR : Crown

** Rating
A : Acceptable N : Not Inspected/Rated
M : Minimally Acceptable C : Corrected
U : Unacceptable A/W : Acceptable but Monitor & Maintain

+ Issue Type
Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

Levee District No. 0001 (Glenn County)

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2014

Levee District No. 0001 (Glenn County)

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	12.23	10/30/2014 10/30/2014	Bob Duffey

LM Start	5.16	Rating **	A/W	Issue No.	7
LM End	5.23	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			39.534741 °	39.535738 °
				-121.996024 °	-121.996570 °
DWR ID	DWR_LD0001G_01_f_2012_7				
Action/Comments					
No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.					

Photo 1 of 1 : FA_2014_LD0001G_432_7_20141013_00004.jpg



View of the rodent hole along the levee slope.

LM Start	5.63	Rating **	M	Issue No.	25
LM End	5.66	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			39.541042 °	39.541454 °
				-121.999276 °	-121.999521 °
DWR ID	DWR_LD0001G_01_s_2012_25				
Action/Comments					
No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.					

No Photos

LM Start	5.99	Rating **	A/W	Issue No.	33
LM End	6.15	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			39.545942 °	39.548203 °
				-122.001185 °	-122.001464 °
DWR ID	DWR_LD0001G_01_f_2014_33				
Action/Comments					
No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

Levee District No. 0001 (Glenn County)

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2014

Levee District No. 0001 (Glenn County)

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	12.23	10/30/2014 10/30/2014	Bob Duffey

LM Start	11.70	Rating **	M	Issue No.	48
LM End	11.70	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			39.622652 °	39.622652 °
				-121.999185 °	-121.999185 °
DWR ID	DWR_LD0001G_01_s _ 2014_48				
Action/Comments					
No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.					

Photo 1 of 1 : FA_2014_LD0001G_432_48_20141013_00015.jpg



View of the rodent activity along the w/s slope.

LM Start	11.82	Rating **	M	Issue No.	42
LM End	11.94	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			39.624171 °	39.625823 °
				-121.999967 °	-122.000834 °
DWR ID	DWR_LD0001G_01_s _ 2012_42				
Action/Comments					
Exterminate rodents and backfill and compact or grout burrows.					

No Photos

LM Start	12.07	Rating **	M	Issue No.	44
LM End	12.13	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			39.627423 °	39.628278 °
				-122.001562 °	-122.001818 °
DWR ID	DWR_LD0001G_01_s _ 2012_44				
Action/Comments					
Elderberries are blocking visibility and flood fight capability.					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---